

Federal Communications Commission

**Before the
Federal Communications Commission
Washington, D.C. 20554**

In the Matter of)	
)	
ConocoPhillips Communications Inc.)	File No. EB-FIELDWR-12-00003202
Antenna Structure Registrant)	
ASR # 1280143)	NOV No. V201232800041
Lysite, WY)	
)	

NOTICE OF VIOLATION

Released: July 18, 2012

By the District Director, Denver District Office, Western Region, Enforcement Bureau:

1. This is a Notice of Violation (Notice) issued pursuant to Section 1.89 of the Commission's Rules,¹ to ConocoPhillips Communications Inc. (ConocoPhillips), registrant of antenna structure # 1280143 in Lysite, WY.

2. On June, 8, 2012, an agent of the Enforcement Bureau's Denver District Office inspected antenna structure # 1280143 located 0.7 miles East of Lysite, WY on Badwater Road and observed the following violations:

- a. 47 C.F.R. § 17.4(g): "Except as described in paragraph (h) of this section, the Antenna Structure Registration Number must be displayed in a conspicuous place so that it is readily visible near the base of the antenna structure. Materials used to display the Antenna Structure Registration Number must be weather-resistant and of sufficient size to be easily seen at the base of the antenna structure." The agent observed that the Antenna Structure Registration Number was not displayed at the time of the inspection on June 8, 2012.
- b. 47 C.F.R. § 17.57: "The owner of an antenna structure for which an Antenna Structure Registration Number has been obtained must notify the Commission within 24 hours of completion of construction (FCC Form 854-R) and/or dismantlement (FCC Form 854). The owner must also immediately notify the Commission using FCC Form 854 upon any change in structure height or change in ownership information." During the inspection, the agent observed that construction of antenna structure # 1280143 had been completed, however, the FCC's antenna structure registration database

¹ 47 C.F.R. § 1.89.

Federal Communications Commission

showed the structure's status as "granted." Since the tower has been built, the status must be changed to "constructed."

3. Pursuant to Section 403 of the Communications Act of 1934, as amended,² and Section 1.89 of the Commission's Rules, ConocoPhillips must submit a written statement concerning this matter within 20 days of release of this Notice. The response must fully explain each violation, must contain a statement of the specific action(s) taken to correct each violation and preclude recurrence, and should include a time line for completion of pending corrective action(s). The response must be complete in itself and signed by a principal or officer of ConocoPhillips. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

Federal Communications Commission
Denver District Office
215 S. Wadsworth Blvd., Suite 303
Lakewood, CO 80226

4. This Notice shall be sent to ConocoPhillips Communications Inc. at its address of record.

5. The Privacy Act of 1974³ requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance. Any false statement made knowingly and willfully in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.⁴

FEDERAL COMMUNICATIONS COMMISSION

Nikki P. Shears
District Director
Denver District Office
Western Region
Enforcement Bureau

² 47 U.S.C. § 403.

³ P.L. 93-579, 5 U.S.C. § 552a(e)(3).

⁴ 18 U.S.C. § 1001 *et seq.*